

Customer No.:  Inspect. rec. No.:  Order No.:



# ELECTRICAL EQUIPMENT TEST REPORT - TEST RESULTS

METREL PAT PRO

Appliance Description	ID	P/F	Retest date	Visual Test	Earth Bond	Insulation	Subleak	Leakage	Touch Leakage	Clamp	Functional Test	PRCD <sup>2</sup>	POL <sup>3</sup>
				(all)	(Ω)	(MΩ)	(mA)	(mA)	(mA)	(A)	(kVA)	(ms)	

**PLAYTIMES**

**MAGIC PHOTOBOOTH**

LIGHTS	90166	P*	09.01.2021	P		>199.9 P	0.02 P						
ACER LAPTOP	90167	P*	09.01.2021	P		>199.9 P	0.06 P						
FLASH BULB	90168	P*	09.01.2021	P		>199.9 P	0.03 P						
CAMERA	90169	P*	09.01.2021	P		>199.9 P	0.02 P						
6WAY EXT	90170	P	09.01.2021	P	0.06 P	>199.9 P							P
8WAY EXT	90171	P	09.01.2021	P	0.05 P	>199.9 P							P
USB HUB	90172	P	09.01.2021	P		>199.9 P		0.01 P			0.01 P		
CANON CHARGER	90173	P*	09.01.2021	P		>199.9 P	0.02 P						
PRINTER	90174	P	09.01.2021	P	0.49 P	>199.9 P	0.92 P						
LAMP	90175	P	09.01.2021	P		>199.9 P		0.02 P			0.01 P		
SONY TV	90176	P*	09.01.2021	P		>199.9 P	0.03 P						

1) Worst result is reported

2) Result of 1xΔN, 0° is reported. If any RCD result failed, a fail (F) is reported

3) Polarity

4) P\* appears if autotest is not completely finished

Signature:  Customer:  Operator: